EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	71	(280/86.758).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/06/28 09:53
L2	122	(280/86.757).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/06/28 09:53
L3	189	(280/86.75).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/06/28 09:53
L4	192	(280/86.751).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/06/28 09:53
L5	94	(280/86.753).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/06/28 09:53
L6	69	(280/86.754).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/06/28 09:53
L7	110	(280/86.756).CCLS.	US-PGPUB; USPAT; USOCR	OR	OFF	2006/06/28 09:53
L8	737	L1 L2 L3 L4 L5 L6 L7	US-PGPUB; USPAT; USOCR	OR	ON	2006/06/28 10:08
L9	14	(cam projections plate washer bolt). clm.	US-PGPUB; USPAT; USOCR	AND	ON	2006/06/28 10:09

6/28/2006 10:10:49 AM Page 1 C:\Documents and Settings\dbrown3\My Documents\EAST\Workspaces\10740202 Toe link adjuster w cam sleeve and plates and washer